

M-12 FOAM TYPE ACID CLEANER

This product is a foaming lactic acid-based cleaner, designed to be used as a manual cleaner for dairy equipment, milking machines and utensils. This product will remove milk stone and hard water scale from all hard surfaces.

DIRECTIONS:

Remove heavy milk stone build-up, dismantle equipment and wash well with an alkaline cleaner. Rinse parts thoroughly. On rubber parts, use a solution of 12 ml/L (1½ oz/gallon) of water and soak parts for 8 hours. Brush parts and rod out tubes until thoroughly clean. Rinse with hot water.

On other parts, use 25 ml/L (4 oz/gallon) of water. Wet all surfaces and soak for 20 minutes. Brush all deposits off surfaces and rinse thoroughly. Then sanitize with a chlorine solution or an iodine solution.

Milk stone Prevention in daily washing operations, use 6 ml/L (1 oz per gallon) of acid cleaner in rinse water after washing with an alkaline cleaner to prevent milk stone build-up.

For Commercial Use Only

